Sindh. Univ. Res. Jour. (Sci. Sr) Vol: 29 (2) 7-18 (1997)

AN ATTEMPT TO INVESTIGATE THE TOUGHNESS ENHANCED HEAT TREATMENT PROCESS FOR LEAF SPRING

Ali Nawaz Memon, Khurshid Abbasi and Ishauqe Abro
Department of Metallurgical Engineering
Mehran University of Engineering & Technology, Jamshoro, Sindh, 76080 Pakistan

Abstract

An investigation has been made for finding the heat treatment process for remarkable enhancement in toughness property of leaf springs. At leaf spring of Bed Ford trucks, being fabricated by All-Win company in Karachi, was selected for manufacture of present work. Before and after the annealing hardening, tempering and austempering heat treatment processes, the hardness, toughness and micro-structures were examined by using Brinell and Rockwell hardness testers, Charpy impact testing machine and optical microscopes.

The results of present work shows that austempering is only toughness enhancing process, which not only shows the remarkable improvement in toughness values but also maintain high hardness without the loss in ductility and consequences of distortion and quench cracks.

Introduction

The heat treatment process is one of the metallurgist tools by means of which, quality, efficiency and reliability of engineering structures is enhanced without altering its design parameters and chemical constituents, so as to achieve structural integrity conveniently.

Depending upon the material and desired mechanical properties, many heat treatments have been developed so for. Among these aneaning, normalizing, hardening, tempering and austempering are the traditional heat treatment processes which are most commonly and extensively used in almost all engineering structure forming industries so as to facilities the commencing fabrication process and to impart he specified mechanical properties as and when desired.

Since the mechanical, physical and chemical properties of engineering structures are specified by the service, conditions. Like wise maximum toughness with considerable hardness value, adequate ductility high fatigue strength and better weldability are the specified properties of leaf spring in order top withstand under the repeated loading conditions and to absorb the millions and trillions of shocks of different altitudes so as to make the soft and comfort riding.

This needs appropriate selection of chemical composition, engineering design, fabrication process and heat treatments. The catastrophic failures of leaf spring in present era-enforce to review the mechanical and metallurgical aspects so as to achieve the goal of high structures integrity.

CamScanner

The present work is just initiation in this regard to review the engineering heat treatment processes and to search out the suitable substituter if possible conveniently by means of which. The quality, efficiency and reliability of engineering structures could achieve.

Material

A leaf of leaf spring was purchased from the shop of autoparts for the present study. The material analysis made from Ship Yard engineering works Karachi reports that the material used for manufacturing of lead spring is AISI 5160 whose chemical composition is reported in table.1

Experimental Methods

1. Specimens for a hardness testing, toughness testing and metallography were prepared as shown in fig.1 from as received leaf of leaf spring. The thickness of all types of specimens is considered same, so that equal soaking time can be maintained. During cutting of specimens the oil as a lubricant was used for subsequent lubrication just to avoid the distortion of micro-structure due to heating.

2. Before subjecting the specimens to heat treatment processes the hardness and toughness values were measured by using Brinell and Rockwell hardness testers and charpy impact testing machine respectively. Besides this the microstructure of as received material was examined (Fig.2) by optical microscope. The results are shown in Table-2.

3. After tabulating the initial results all specimens for hardness, impact and metallography were annealed, hardened, tempered and austinitized. The general characteristics of each process exercised during present work is as under.

Annealing Characteristics

Critical Temperature	85° C
Soaking Time	5 Min.
Quenching Media	Furnace Cool

After 24 hours the annealed specimen were tested. The results are shown in table 3 and fig. 3

Hardening Characteristics

Critical Temperature	85°C
Soaking Time	I Min/mm thickness
Quenching Media	Oil

The tests were conducted whose results are shown in Table 4 and fig.4

CamScanner

Tempering Characteristics

Just after hardening process the specimens were tempered at 450°C, 500°C and 550°C for one hour in the oil media. The results are shown in Table 5 and fig 5

Tempering Characteristics

Critical Temperature	850°C
Sub-Critical Temperature	340°C
Nature of Salt	55% KN 03+45% $NaNO_3$
Soaking Time	1 Hour
Quenching Media	Oil

The results of austempered specimen are shown in table 6 and fig. 6.

Results and Discussion

The results of annealing, hardening, tempering and austempering are shown in table 3,4,5, & 6 and Fig. 5,6,7 & 8.

It is very clear that enhancement in toughness value is none in annealing than the austempering and hardening followed bu tempering. But it is not fit for leaf spring due to the loss in hardness which is so severe side effect that one can not compromise with it. On the other hand hardening and tempering tough improves the hardness value but decrease the toughness.

In fact the hardness and roughness properties of material are inversely related with each other 2,3,4 that is why one improves at the compensate of other. Due to this reason neither annealing for hardening or tempering shows +ve effect on both properties. Austempering on the other hand seems to be suitable heat treatment process which not only shows the remarkable enhancement in the toughness value but also improves hardness value. This is because of the fact that austermpering process is neither merely thermal process for isothermal is purely the isothermal process which gives too soft microstructure (i.e. pearlite), while the hardening is a thermal process which give birth to hard microstructure (i.e. martensite). Though the tempering to had microstructure (i.e. sorbite) but fails to provide highly tough micro structure. However in the austermpering process both thermal and thermal principles works simultaneously due to which neither austenite decompose into soft microstructure nor hard, but in between hard and soft. The by-product of austenite due to austempering is bainite, which shows good balance and compromise between toughness and hardness than any other micro structure. Almost zero probability to quench cracks or distortion is an additional attraction for attempering. The intermediate cooling rates are the basic reasons behind this fact. Thus the chance of strained microstructure during austempering approaches to zero.

CamScanner

Conclusion

It is concluded from present work that austempering is only toughness enhancing process while retaining the high value of hardness. In the light of the present work the authors recommend the austempering process of leaf spring than the hardening followed by tempering as being practice by Allwin Company.

References

1. Mr. Abro, Mr. Memon, Mr. Abbasi "Failure Analysis of Leafspring "S.U.R. JOURNAL" Vol. 29 (1), 83-88, (1997)
2. F.B. Pickering, "Proceedings of International Sumposium on high Strength low Alloy Steel " Oct. 1975.
3. M.J. Robberts, "Effects of Transformation Substructures on the Strength and Toughness of Fe-Mn Alloys" Met Trans, Vol. 1970, P-3291
4. V.F. Zackay, E.R. Parker, D. Fahr and R.Bush, "The Enhancement of Ductility in High Strength Steels" Trans ASM Vol.61, 1969, P-843
5. S.D. Auto Lovich and B.Singh, "On the Roughness Increasement Associated with the Austenite Phase Transformation in TRIP Steels" Met Trans, Vol.2, 1971, P-2135.
6. Avener, "Physical Metallurgy".
7. Hony Comn. "Steels Microstructure and Mechanical Properties".

CamScanner

TABLE : 1

CHEMICAL COMPOSITION IN WT%

S.NO.	ELEMENT	%AGE OF WEIGHT
01.	Carbon	0.5 to 0.5
02.	Manganese	0.65 to 0.95
03.	Silicon	0.15 to 0.35
04.	Chromium	0.6 to 0.95
05.	Phosphorus	0.035
06.	Sulfur	0.033

TABLE : 2

MECHANICAL PROPERTIES OF AS RECEIVE SPECIMEN

Brinell Hardness No.	387.6 BHN
Rockwell Hardness No.	40 HRC
Toughness	1.2 kg mm
Microstructure	Sorbite

CamScanner

TABLE : 3

MECHANICAL PROPERTIES AFTER ANNEALING

Sr. No.	Brinell Hardness	Rock Wall Hardness	Toughness	Microstructure
01.	125.97	13.5	03	Pearlite
02.	125.0	13.1	3.2	Pearlite
03.	125.5	13.2	3.0	Pearlite

TABLE : 4

MECHANICAL PROPERTIES AFTER HARDENING

Sr. No.	Brinell Hardness	Rock Wall Hardness	Toughness	Microstructure
01.	532.95	55	1.0	Martensite
02.	532.5	54.6	1.0	Martensite
03.	533.5	55.9	1.0	Martensite

CamScanner

TABLE : 5

MECHANICAL PROPERTIES AFTER TEMPERING

Sr. No.	Tempering Temperature	Brinell Hardness	Rock Wall Hardness	Toughness	Microstructure
01.	450	406.98	42	1.2	Martensite
02.	450	406.5	42	1.2	Martensite
03.	450	405.0	41	1.2	Martensite
01.	500°C	357.6	40	1.29	Laminated Sorbite
02.	500°C	357.4	40	1.29	Laminated Sorbite
03.	500°C	357.0	39.5	1.29	Laminated Sorbite
01.	500°C	375.97	38.0	1.35	Sorbite
02.	500°C	375.6	38.7	1.36	Sorbite
03.	500°C	375.00	38.2	1.39	Sorbite

TABLE : 6

MECHANICAL PROPERTIES AFTER AUSTEMPERING

Sr. No.	Brinell Hardness No.	Rockwell Hardness No.	Toughness	Microstructure
01.	465.12 BHN	49.5 HRC	1.95 kg/mm	Bainite
02.	463.99 BHN	48.5 HRC	1.95 kg/mm	Bainite
03.	464.52 BHN	47.5 HRC	1.95 kg/mm	Bainite
Mean Results 464.54 BHN		48.3 HRC	1.83 kg/mm	

CamScanner




FIG:2 SORBIT MICROSTRUCTURE OBSERVED AT 400 MAG:




FIG:3 PEARLITE MICROSTRUCTURE OBSERVED AFTER ANNEALING AT 400 MAG.




Fig. 1 MARTENSITE STRUCTURE OBSERVED AFTER HARDENING AT 900 DIA.




Fig. 2 MARTENSITE MICROSTRUCTURE OBSERVED AFTER TEMPERING AT 450 C AT 400 DIA.




FIG:5b LAMINATED SORBITE MICROSTRUCTURE OBSERVED AFTER TEMPERING AT 500 C AT 400 MAG.






FIG:5C SORBITE MICROSTRUCTURE OBSERVED AFTER TEMPERING AT 550 C AT 400 MAG.


CamScanner



[illegible] POWER SCANNING MICROSTRUCTURE OBSERVED AFTER AUS-
o
TEMPERING AT 345 C AT 100 MPa.







(a) TOUGHNESS SPECIMEN.
(b) HARDNESS SPECIMEN.
(c) METALLOGROPHY. SPECIMEN.